

PLASMA CUTTING

Serie ZETA® HF



















CE EN60974-7







CODE	↔		☐
PAH006D-000-FA3	6 m	19.7'	
PAH008D-000-FA3	7,6 m	25'	
PAH015D-000-FA3	15,2 m	50'	
PAH006D-004-FA3	6 m	19.7'	
PAH008D-004-FA3	7,6 m	25'	
PAH015D-004-FA3	15,2 m	50'	
PAH006D-304-FA3	6 m	19.7'	
PAH008D-304-FA3	7,6 m	25'	
PAH015D-304-FA3	15,2 m	50'	

TECHNICAL DATA						
	HF	40 A	60 A	80 A	110 A	130 A
		0,4 kg	0,4 kg	0,4 kg	0,4 kg	0,4 kg
		0,88 lb	0,88 lb	0,88 lb	0,88 lb	0,88 lb
	PEAK	500	500	500	500	500
		5 bar	5 bar	5 bar	5 bar	5 bar
		110 l/m	120 l/min	140 l/min	155 l/m	180 l/m
	X 60%	40A	60A	80A	110A	130A
	X 100%	30A	45A	65A	85A	105A
		15 mm	25 mm	32 mm	40 mm	45 mm
		3/5"	1"	1 1/4"	1 3/5"	1 3/4"



CODE	Ø	↔	STARTER KIT					PCS x 	 x 	
			PT1040	PT1060	PT1080	PT1110	PT1130			
			40 A	60 A	80 A	110 A	130 A			
1	CV0363P								1	2
1	CV0364P								1	2
1	CV0365P								1	2
2	PC0360P								1	2
3	PD0360P08								5	2
3	PD0360P10								5	2
3	PD0360P13								5	2
3	PD0361P15								5	2
3	PD0362P17								5	2
4	PE0360P								1	2
5	PR0360P								5	2
5	PR0361P								5	2
6	FH1602P								1	2

CODE			
7	EA1920		
7	PF0370		
8	BX0910		
8	PT0361		
8	PT0362		
9	TP0370	1	
10	PH0908-06	6m - 1/4 G	1
10	PH0908-08	7,6m - 1/4 G	1
10	PH0908-15	15m - 1/4 G	1
11	BW0147	cable support	1
11	FY0043	Central Adaptor	1
12	FY0090	TRAFIMECTOR®	1

CODE	GOUGING	40 A	60 A	80 A	110 A	130 A	PCS x 	 x 
1	CV0370P						1	2
1	CV0371P						1	2
1	CV0372P						1	2
3	PD0370P16						5	2
3	PD0370P18						5	2
3	PD0370P20						5	2
3	PD0370P22						5	2